



healthmark  
INDUSTRIES CO.  
health care products

33671 Doreka  
Fraser, Michigan 48026  
Telephone: (586) 491-2002  
Fax: (586) 491-2112  
www.HMARK.com

## SHOCKER! HEALTHMARK COMES CLEAN!



## ADMITS THE TOSI IS BIASED!

We admit it. It's true what some have said. The TOSI is biased.

The TOSI is dried blood soil on a stainless steel coupon. It is just like dried blood on a stainless steel surgical instrument. We mount the plate in a plastic holder with a graduated gap. This is just like the areas on a surgical instrument which are blocked from direct spray action, such as the box locks.

So you see, the TOSI is biased. It is biased toward products and methods that are effective at cleaning blood off of stainless steel instruments. This includes alkaline and enzyme detergents; high and low flow washers; high and low impingement washers; and washers made in North America, Europe, and Asia. If your washer is not getting the TOSI clean, it is not the washer or detergent type, but something in the setup or operation. And the TOSI can help you identify and diagnose the source of the problem. To learn more, visit [TOSI-Test.com](http://TOSI-Test.com).

So the next time someone tells you the TOSI is not meant for their product, ask them, "Is your product not meant to clean blood from stainless steel surgical instruments?"

Keeping it Clean,

***Ralph J. Basile***

Ralph J. Basile

Vice President