


## Steriking 2P packages EO and steam process indicator's reference color chart

The Steriking process indicators provide clear, contrasting color changes. Color change may vary due to differences in processing parameters. The indicators should not be exposed to direct light prior to use.

### STEAM-indicator:

Reference Start Colors




Reference End Colors



### EO-indicator:

Reference Start Colors



Reference End Colors



Please NOTE: This list of reference colors is not all inclusive.